



BLE Temperature & Humidity Sensor

Install with 3M tape, screw holes or magnet mount

Press & Hold On/Off button approx 3 secs to turn on or off. A red LED will appear at the front (behind the vents). Turn on prior to use!

Be sure to not block the vents.

